PRESSOCHECK



FIT IT



DON THE MASK - Put the straps and to a suitably tight and comfortable fit.

PRESS IT



PRESSTOCHECK[™] - Press the front and backs of both filter covers together to stop air from entering through the filters.

CHECK IT



INHALE - No air should come through the mask. 1 look forward and adjust the mask until a seal is created. Repeat this process whilst looking (2) up, (3) down, (4) left and (5) right.

PRESS TO CHECKTM IN CARTRIDGE EIITEDC DANCE

FILIEKS KANGE		P3	A2 P3	ABEK1 P3
Organic vapours (>WEL*)	(A)			
Inorganic vapours (>WEL*)	(B)			
Acidic vapours (>WEL*)	(E)			
Ammonia vapours (>WEL*)	(K)			
Nuisance odours (<wel*)< td=""><td></td><td></td><td></td><td></td></wel*)<>				
Dusts	(P)	Very Fine	Fine	Fine
Mists				
Water based painting				
Solvent based brush painting)			
Rubbing down paint		Power Tool		
Paint stripping, chemical or	neat			
White spirit				
Chlorine (cleaning & pools)				
Glyphosate (weed killer)				
Brick acid (graffiti removal)				
Formaldehyde				
Fibres & fibre glass				
Plaster				
Silica (concrete/stone cutting)			
Woods (hard & soft)				
MDF (machine tooling)				
Welding (ferrous & lead)				
Earth moving (contaminated)				

SCAN ro find **OUT MORE...**





Readily available guide to suitable applications for PressToCheck™



Fitting and demonstration videos for **PressToCheck**[™]

*Wel (Workplace exposure Level)- This table is for guidance purposes only.

A proper risk assessment by qualified personnel should be carried out before selecting an appropriate filter cartridge